




Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D2576-3
Job Sheet 213875



Part No: D2576-3

Job Qty: 50 pcs

Part Name: Step (Machining Detail)



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 10/8/20

Job Tracking No:

Created By: Jennifer Renwick

Due Date: 10/26/20

Description: SIOP

Type: Stock

Note: DWG REV G IPP: E 02.08.19 Consolidated D2576-1 and D2576-3 KJ/RF IPP Rev:D As per Rev G 07-09-05
JLM Verified By:EC

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
100	HAAS 4 Axis	50 pcs		10/26/20	0.03	8.33	HAAS - 1		JIP 20-10-14
							HAAS - 2		
							HAAS - 3		
							HAAS - 4		
110	QC 2	50 pcs		10/26/20	0.00	0.00	QC 2 - 1		
							QC 2 - 12		
							QC 2 - 14		
							QC 2 - 17		
							QC 2 - 19		
							QC 2 - 2		
							QC 2 - 20		
							QC 2 - 22		
							QC 2 - 23		
							QC 2 - 25		
							QC 2 - 32		
							QC 2 - 33		
							QC 2 - 35		
							QC 2 - 39		
							QC 2 - 4		
							QC 2 - 40		
							QC 2 - 44		
							QC 2 - 45		
							QC 2 - 48		
							QC 2 - 49		
							QC 2 - 50		
							QC 2 - 51		
							QC 2 - 52		
							QC 2 - 57		
							QC 2 - 62		
							QC 2 - 63		



Container No: S306413



Part: D2576-3

Job No: 213875

Serial No/Batch: S306413

Revision:

Inspector:

Exp Date:

Instructions: Various STC's

Date: 10/14/20

Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON K6A 1K7
CANADA
TEL: 1 613 632-5200
Email: sales@artaero.com
www.dartaero.com


Plex 10/8/20 10:26 AM Dart.Renwick.Jennife

				QC 2 - 8	
				QC 2 - 66	
				QC 2 - 64	
				QC 2 - 65	
				QC 2 - 5	
				QC 2 - 71	
				QC 2 - 73	DJP 20-10-14
				QC 2 - 69	
				QC 2 - 76	
				QC 2 - 86	
				QC 2 - 83	
120 QC 8	50 pcs	10/26/20	0.00 0.00	QC 8 - 12	
				QC 8 - 14	
				QC 8 - 17	
				QC 8 - 20	
				QC 8 - 25	
				QC 8 - 3	
				QC 8 - 32	
				QC 8 - 33	
				QC 8 - 35	
				QC 8 - 39	
				QC 8 - 4	
				QC 8 - 44	
				QC 8 - 45	
				QC 8 - 49	
				QC 8 - 58	
				QC 8 - 8	B.e 20-10-17
				QC 8 - 9	
				QC 8 - 68	
				QC 8 - 67	
				QC 8 - 1 (A)	
				QC 8 - 47	
				QC 8 - 40	
				QC 8 - 52	
				QC 8 - 23	
				QC 8 - 57	
				QC 8 - 76	
				QC 8 - 61	
				QC 8 - 66	
				QC 8 - 73	
				QC 8 - 82	
130 Packaging 3-1 - Stock - B4B	50 pcs	10/26/20	0.00 0.00	Packaging 3 - 1 - B4B	
				Packaging 3 - 2 - B4B	
				Packaging 3 - 3 - B4B	
				Packaging 3 - 4 - B4B	
				Packaging 3 - 5 - B4B	
				Packaging 3 - 6 - B4B	
				Packaging 3 - 7 - B4B	
				Packaging 3 - 8 - B4B	
				Packaging 3 - 9 - B4B	
				Packaging 3 - 10 - B4B	
				Packaging 3 - 11 - B4B	
				Packaging 3 - 12 - B4B	
				Packaging 3 - 13 - B4B	
				Packaging 3 - 14 - B4B	
				Packaging 3 - 15 - B4B	
				Packaging 3 - 16 - B4B	
				Packaging 3 - 17 - B4B	
				Packaging 3 - 18 - B4B	


Plex 10/8/20 10:26 AM Dart.Renwick.Jennife

					Packaging 3 - 19 - B4B	
					Packaging 3 - 20 - B4B	
					Packaging 3 - 21 - B4B	
					Packaging 3 - 22 - B4B	
					Packaging 3 - 23 - B4B	
					Packaging 3 - 24 - B4B	
					Packaging 3 - 25 - B4B	
					Packaging 3 - 26 - B4B	BE OCT 20 2020
					Packaging 3 - 27 - B4B	
					Packaging 3 - 28 - B4B	
					Packaging 3 - 29 - B4B	
					Packaging 3 - 30 - B4B	
					Packaging 3 - 31 - B4B	
					Packaging 3 - 32 - B4B	
					Packaging 3 - 33 - B4B	
					Packaging 3 - 34 - B4B	
					Packaging 3 - 35 - B4B	
					Packaging 3 - 36 - B4B	
					Packaging 3 - 37 - B4B	
140	QC 21 - SA	50 pcs	10/26/20	0.00 0.00	QC 21 - SA - 21	
					QC 21 - SA - 70	DAS
					QC 21 - SA - 9	21
					QC 21 - SA - 77	9-89
					QC 21 - SA - 28	
Part Op 100 - (HAAS CNC vertical machine #1) HAAS 1 1- Machine as per Folio FA332 and Dwg D2576 2- Deburr Descriptions: 110 - (QC2- Inspect parts off machine FAI/FAIB) 120 - (QC8- Inspect parts - second check) 130 - (Identify as per dwg & Stock Location: <u>Loc 4</u>) ***STOCK IN SKIDTUBE CELL*** LOCATION : LG001 140 - (QC21- Final Inspection - Work Order Release)						
Job BOM						
Part / Item	Component Name	Quantity	Operation	Container		
D2576-1	Step (Casting Detail)	50 pcs (1 ea)	100-HAAS 4 Axis	S202013		
Job Allocations						
Operation	Component Part	Required	Inventory	Allocated		
100-HAAS 4 Axis	D2576-1	50	57	0		
Part Specifications						
Specifications could not be found.						

Plex 10/8/20 10:26 AM Dart.Renwick.Jennifer



D2576-1 CASTING



D2576-3 MACHINING DETAIL
(MAKE FROM D2576-1)

- NOTES:**
- 1) MATERIAL: CAST ALUMINUM ALLOY A-535.2
 - 2) FINISH: NONE
 - 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
 - 4) UNITS: INCHES UNLESS OTHERWISE NOTED
 - 5) BREAK SHARP EDGES: 0.025 TO 0.050 MAX
 - 6) IDENTIFICATION: NONE

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 213875

RELEASED

07.08.21

G	- CHANGE SLOTS LOCATION AND SIZE ON D2576-3 - DUE TO SKID BENDING PROGRAM CHANGES - UPDATE CNC PROGRAM	MB	07.08.15
F	7.05 WAS 6.61	PH	07.04.17
E	CHANGE 0.50 HOLE LOCATION AND ADD NOTE	RF	99.09.07
D	CHANGE SLOT SIZE AND LOCATION (TSR A1069)	CP	99.08.18
C	ADD POCKETS AND SLOTS FOR WELDING	DS	98.08.18
B	REMOVE POCKETS, ADD HOLE	DS	96.11.28
A	NEW ISSUE	DS	96.09.18
REV.	DESCRIPTION	BY	DATE
DESIGN			
DRAWN			
CHECKED			
MFG. APPR.			
APPROVED			
DE APPR.			
DATE	07.08.15		
DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA DRAWING NO. D2576 TITLE STEP REV. G SHEET 1 OF 1 SCALE 1:3 COPYRIGHT © 1996 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.			

420
40
460mm

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐			
Date :	Sequence #:	QTY Affected :		MRB (QSI042)	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor	
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Presservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐ ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled		FAULT CATEGORY ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread			
Other/Details:					